

# SENSOR INSTALLATION ACCESSORIES

## UNI-STRUT® MOUNTING KIT

Installation kit for installing the DDS, DTS, and DMS sensors in sump space.

### HIGHLIGHTS

- Easily customized to fit virtually any sump by cutting the Unistrut™ assembly to desired length.
- Provided with 2", 3", and 4" pipe clamps for mounting to sump piping.
- Sensor location easily adjusted by the unique sliding feature of the Unistrut™ assembly.

Model	Description
TSP-KS	Unistrut™ mounting kit for TSP-DDS and TSP-DTS sensors

### SENSOR INSTALLATION ACCESSORIES

Model	Description
TSP-DB1	One direct burial splice connector kit
TSP-DB10	Pack of 10 direct burial splice connector kits
TSP-DBTOOL	Epoxy dispensing tool
TSP-KW30	Pack of 30 3M™ splice connectors

**Notes:**

1. Use the TSP-DB1 or TSP-DB10 for direct burial cable applications or when weatherproof junction boxes are not used.
2. The DBTOOL is required to dispense the epoxy.
3. Each direct burial splice connector kit includes a receptacle, three splice connectors, and epoxy for the dispensing tool.